

S.No	Item	Progress during quarter ended 30.09.2017	Progress during quarter ended 31.12.2017
1	Reception Entrance lobby at Ground Floor	10%	17%
2	Fire Fighting and Domestic water supply equipment	0%	0%
3	Water supply for Overhead tanks	0%	0%
4	Water supply connection provision from main HUDA line	0%	0%
5	Underground domestic and fire water tanks and pump room	15%	20%
6	Electric Substation/transformers/electrical panels	0%	0%
7	Rain water Harvesting pits	0%	0%
8	Maintenance office/service areas	0%	0%
9	lawns and play areas,including lighting and services	0%	0%
10	Guard Room	0%	0%
11	Garbage room	0%	0%
12	Approach road to apartment buildings,E.W.S building,Community Centre,Schools and Convinient Shopping	0%	0%
13	Green Landscaape Areas,Water bodies,Fountain and lighting/Service thereof	0%	0%
14	Main Gate	0%	0%
15	Boundary wall	0%	10%
16	Driveways/roads/walkways/lighting and services	0%	0%
17	Boom Barrier at main entrance and exit	0%	0%
18	Storm water drainage line	0%	0%
19	Sewerage Drainage line	0%	0%
20	Sewerage treatment plant	15%	20%
21	Servant/Driver's toilet	0%	0%
22	Staircases,lobbies,mumties,passages,and landings of indivdual buildings	20%	40%
23	lifts/lift's shaft and LMR with equipment	10%	15%
24	Overhead tanks	30%	50%
25	lightening protection/arrestor and aviation caution lights	0%	0%
26	Common passages/corridors including lighting and firefighting equipment thereof	0%	0%
27	Power Distribution Sysytem,Sub Station including DG Sets loacated in basements	0%	0%
28	Security and Fire control room with Fire detection system/PA System	0%	0%
29	Ramp Driveways/Staircases/Passage/Shfts/Ducting( Basement ventilation),Lighting and services thereof in basement	10%	25%
30	Sump Pumps	0%	0%

31	Sprinkler and ventilation System in Basement	0%	0%
32	Fire detection system	0%	0%