

S.No	Item	Progress during quarter ended 30.09.2017	Progress during quarter ended 31.12.2017
1	Reception Entrance lobby at Ground Floor	-	-
2	Fire Fighting and Domestic water supply equipment	-	-
3	Water supply for Overhead tanks	-	-
4	Water supply connection provision from main HUDA line	-	-
5	Underground domestic and fire water tanks and pump room	-	-
6	Electric Substation/transformers/electrical panels	-	-
7	Rain water Harvesting pits	0%	5%
8	Maintenance office/service areas	-	-
9	lawns and play areas,including lighting and services	-	-
10	Guard Room	-	-
11	Garbage room	-	-
12	Approach road to apartment buildings,E.W.S building,Community Centre,Schools and Convinient Shopping	-	-
13	Green Landscaape Areas,Water bodies,Fountain and lighting/Service thereof	-	-
14	Main Gate	-	-
15	Boundary wall	-	-
16	Driveways/roads/walkways/lighting and services	-	-
17	Boom Barrier at main entrance and exit	-	-
18	Storm water drainage line	-	-
19	Sewerage Drainage line	0%	2%
20	Sewerage treatment plant	-	-
21	Servant/Driver's toilet	-	-
22	Staircases,lobbies,mumties,passages,and landings of indivdual buildings	-	-
23	lifts/lift's shaft and LMR with equipment	0%	50%
24	Overhead tanks	0%	10%
25	lightening protection/arrestor and aviation caution lights	-	-
26	Common passages/corridors including lighting and firefighting equipment thereof	-	-
27	Power Distribution Sysytem,Sub Station including DG Sets loacated in basements	-	-
28	Security and Fire control room with Fire detection system/PA System	-	-
29	Ramp/Driveways/Staircases/Passage/Shfts/Ducting(B asement ventilation),Lighting and services thereof in basement	-	-
30	Sump Pumps	-	-
31	Sprinkler and ventilation System in Basement	-	-
32	Fire detection system	-	-