

S.No	Item	Progress during quarter ended 30.09.2017	Progress during quarter ended 31.12.2017
1	Reception Entrance lobby at Ground Floor	10%	24%
2	Fire Fighting and Domestic water supply equipment	5%	20%
3	Water supply for Overhead tanks		-
4	Water supply connection provision from main HUDA line		-
5	Underground domestic and fire water tanks and pump room		-
6	Electric Substation/transformers/electrical panels		-
7	Rain water Harvesting pits	35%	80%
8	Maintenance office/service areas		
9	lawns and play areas,including lighting and services		
10	Guard Room		
11	Garbage room		-
12	Approach road to apartment buildings,E.W.S building,Community Centre,Schools and Convinient Shopping		
13	Green Landscaape Areas,Water bodies,Fountain and lighting/Service thereof		-
14	Main Gate		
15	Boundary wall		40%
16	Driveways/roads/walkways/lighting and services		
17	Boom Barrier at main entrance and exit		
18	Storm water drainage line	5%	30%
19	Sewerage Drainage line	5%	30%
20	Sewerage treatment plant		-
21	Servant/Driver's toilet		
22	Staircases,lobbies,mumties,passages,and landings of individual buildings	40%	60%
23	lifts/lift's shaft and LMR with equipment	40%	60%
24	Overhead tanks	40%	60%
25	lightening protection/arrestor and aviation caution lights		
26	Common passages/corridors including lighting and firefighting equipment thereof		10%
27	Power Distribution Sysytem,Sub Station including DG Sets loacated in basements	15%	60%
28	Security and Fire control room with Fire detection system/PA System		5%
29	Ramp Driveways/Staircases/Passage/Shafts/Ducting(Basement ventilation),Lighting and services thereof in basement		15%
30	Sump Pumps		-
31	Sprinkler and ventilation System in Basement		15%
32	Fire detection system		25%